WATER TEST REAGENT

Form G-1 4/78

For Laboratory Use Only SMALL VOLUMES USED

CONTAINER SIZE RANGE MA	ATERIA	AL SAFET	Y DAIA SHEET		
● Section 1 - PRODUCT IDENTIF	ICATION	V			
MANUFACTURER'S NAME DEARBORN CHEMICAL CO., S	ry, W. R. Grace & Co.		EMERGENCY PHONE NO. 312/438-8241		
ADDRESS 300 Genesee St., L≎ke Z	urich,	IL 60047			
CHEMICAL NAME AND SYNONYMS Nitrite indicator	TRADE NAME OR CODE IDENT. Code 590				
Section 2 – INGREDIENTS		CAS	No. %	EXPOSURE CRITERIA	
	NON - HAZARDOUS MATERIAL The product identified in this Data Sheet is NOT a hazardous material within the meaning of Title 29, Code of Federal Regulations 1915, 1916, 1917.				
Ferroin aqueous solut	ion		100.0%		
 Section 3 — PHYSICAL DATA 	· - · · · · · · · · · · · · · · · · · ·	, , , , , , , , , , , , , , , , , , , 			
BOILING POINT, 760mm Hg		11/1	MELTING POINT		NA
SPECIFIC GRAVITY (H ₂ 0 = 1)		i_0	VAPOR PRESSURE		UK
POR DENSITY (AIR = 1)		'U	SOLUBILITY IN H ₂ O, % E	BY WT.	Complete
% VOLATILES BY VOLUME		4	EVAPORATION RATE,	= 1	UK
APPEARANCE AND ODOR Dark red		рН		UK	
 Section 4 — FIRE AND EXPLOS 	SION HA	ZARD DATA			
FLASH POINT (and Method Used) None			LIMITS in AIR, % by VOLUM UPPER	ME AUTO IGNITIO	N TEMPERATURE
EXTINGUISHING MEDIA 🔲 Water Fog		Foam	□ CO ₂ □ Dry Chem	ical Oth	3r
SPECIAL FIRE FIGHTING PROCEDURE	ES	none	-· -·		·
UNUSUAL FIRE AND EXPLOSION HAZ	ZARD	\rightarrow	lone.	-	
 Section 5 – REACTIVITY DATA 	A				
STABILITY (Normal Conditions)	CONDITI	ONS TO AVOID			
x□ Stable □ Unstable			pone	. ,	
INCOMPATIBILITY (Materials to Avoid)		none			_
142ARDOUS DECOMPOSITION PROD	UCTS		none	· · · · · · · · · · · · · · · · · · ·	
HAZARDOUS POLYMERIZATION	CONDI	TIONS TO AVOI	D .		

(over)

 Section 6 THE/ EXPOSURE LIMIT 	ALTH HAZARD INFORMATION	
	Not established	
EFFECTS OF OVERE	YPOSTIBE	
INHALATION	AT OSONE	
	Not expected	the second of
	•	· .(
	•	
INGESTION		
	Not expected. Not for inte	ernal use.
•		
	•	
SKIN OR EYE COM	= .	
wash skin and	eyes with clear water. If e	eye irritation occurs, contact physician.
EMERCENCY AND S	IRST AID PROCEDURES	
- CIMENGENCE MIND P	•	
***	2	le above
• Section 7 SPE	CIAL PROTECTION INFORMATIO) (1)
VENTILATION REQU	HOSMENITS	
VENTER FOR REGE	Sn.	letanical
	<u> </u>	
RESPIRATORY PROT	(ECTION (Specify Type)	
	. , , , , , , , , , , , , , , , , , , ,	
EYE PROTECTION	Safety glasses	GLOVES (Specify Type)
	ourcey grasses	none
OTHER PROTECTIVE	CLOTHING AND EQUIPMENT (Specify	Type)
• Section 8 - SPII	LL OR LEAK PROCEDURES	
	IF MATERIAL IS RELEASED OR SPILL	
Use absorbe	nt paper towel and discard in	waste container. Rinse area of spill with wate
WASTE DISPOSAL M	ETHOD	
Dispose sma	ll amounts to drain using lar	ge amount of water to dilute. Dispose of larger
amounts by	placing capped bottle in cont	ainer for authorized chemical scavenger service
 Section 9 – SPE 	CIAL PRECAUTIONS	
PRECAUTIONS TO B	E TAKEN IN HANDLING AND STORAGE	E
Protect con	tainer from physical damage.	Keep closed when not in use.
OTHER PRECAUTION		
•	•.	
Shipping Name: DOT	Chemicals, NOI, Water Testi	ng Reagents - NOT RESTRICTED
IATA		
		Prepared By W. M. Morris
		9/70
	•	Date: 8/79
		`